

1994 GALION 850 AWD

Customer Owned

MOTOR GRADERS

Inspection
Number: 1679521
SMU/Hrs: 11,853

Serial #: U201027

Features

- EROPS
- AIR CONDITIONER
- CAB, HIGH PROFILE
- SIDE SHIFT
- TIP CONTROL
- DIFF LOCK/UNLOC
- ALL WHEEL DRIVE
- ENGINE ENCLOSURES
- SLIPCLUTCH
- LIGHTING

Condition

.GENERAL APPEARANCE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Poor - Bolt holes broken out of fan guard			<input type="checkbox"/>	
Eng. Enclose Hood / Stack	Good			<input type="checkbox"/>	
Fuel Tank	Good			<input type="checkbox"/>	
Crankcase Guard / Battery Box	Good			<input type="checkbox"/>	
Draw Bar	Good			<input type="checkbox"/>	
Front Frame	Good			<input type="checkbox"/>	
Rear Frame	Good			<input type="checkbox"/>	
Bumper	Good			<input type="checkbox"/>	
Pre-Cleaner Bowl	Fair - bented			<input type="checkbox"/>	
Cab or Canopy	Good			<input type="checkbox"/>	
Steps / Ladder	Good			<input type="checkbox"/>	
Grab Irons	Good			<input type="checkbox"/>	
Paint	Fair - worn old			<input type="checkbox"/>	
Sheet Metal	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
S.O.S. Taken	No			<input type="checkbox"/>	
Cleaning Required	Yes			<input type="checkbox"/>	

.SAFETY ITEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Safety Decals In Place	Yes			<input type="checkbox"/>	
Safety Decals Legible	Yes			<input type="checkbox"/>	
Rotating Beacon	Yes - inop			<input type="checkbox"/>	
Signal Lights	Yes - both front signal lights broken and inop			<input type="checkbox"/>	
ROPS	Yes - holes drilled in rops			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Poor - inop			<input type="checkbox"/>	

.GAUGES, OPERATOR STATION, CONSOLE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Dash Console	Good			<input type="checkbox"/>	
Gauges	Good			<input type="checkbox"/>	
Switches	Good			<input type="checkbox"/>	
Windshield Wipers	Fair - blades need replaced front washer nozzle broken			<input type="checkbox"/>	
Heater	Good			<input type="checkbox"/>	
Interior Lights	Good			<input type="checkbox"/>	
Seat Cushion / Arm Rest	Fair - worn burn holes			<input type="checkbox"/>	
Floor Boards	Fair - worn			<input type="checkbox"/>	
EMS Panel / Warnings	Good			<input type="checkbox"/>	
Door Latches	Poor - left side broken off right side will not open			<input type="checkbox"/>	

Glass/Mirrors	Good			<input type="checkbox"/>	
Air Conditioner	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Current Parts Manual	No			<input type="checkbox"/>	
Current Safety Manual	No			<input type="checkbox"/>	
Current O&MM	No			<input type="checkbox"/>	
Seat Belt	Yes - out of date			<input type="checkbox"/>	
Back Up Alarm	Yes - inop			<input type="checkbox"/>	
ROPS Certification Plate	Yes			<input type="checkbox"/>	

.ENGINE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	Yes - oil sender leaking oil pan leaking			<input type="checkbox"/>	
Blow By	No			<input type="checkbox"/>	
Knocking	No			<input type="checkbox"/>	
Compression in Radiator	No			<input type="checkbox"/>	
Water in Oil	No			<input type="checkbox"/>	
Fluid Levels OK?	Yes			<input type="checkbox"/>	
EPA Decal	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Anti-Freeze Color	green			<input type="checkbox"/>	
Oil Pressure (H/L/N)	ok			<input type="checkbox"/>	
Smoke (B/D/L/W)	ok			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Operating Condition	Good			<input type="checkbox"/>	

Turbocharger / Blower	Fair - return lines leaking			<input type="checkbox"/>	
Fuel Injection System	Good			<input type="checkbox"/>	
Governor	Good			<input type="checkbox"/>	
Engine Supports	Good			<input type="checkbox"/>	
Air Cleaners	Good			<input type="checkbox"/>	
Exhaust / Muffler	Good			<input type="checkbox"/>	
Oil Filter Condition (CUT)	Good			<input type="checkbox"/>	
Belts / Pulleys	Good			<input type="checkbox"/>	

.COOLING SYSTEM.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator	Good			<input type="checkbox"/>	
Coolers	Good			<input type="checkbox"/>	
Hoses	Fair - seeping			<input type="checkbox"/>	
Water Pump	Good			<input type="checkbox"/>	
Fan	Good			<input type="checkbox"/>	
Fan Drive	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	Yes			<input type="checkbox"/>	

ELECTRICAL, STARTING AND CHARGING SYSTEM.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Batteries / Cables	Good			<input type="checkbox"/>	
Starter	Good			<input type="checkbox"/>	
Alternator	Good			<input type="checkbox"/>	
Wiring	Good			<input type="checkbox"/>	

Lighting	Good - some lights inop			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Ether Aid	Yes			<input type="checkbox"/>	
Block Heater	Yes			<input type="checkbox"/>	

.TRANSMISSION.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Type	Good - power shift			<input type="checkbox"/>	
Case	Fair - case has leak on right side of trans needs resealed			<input type="checkbox"/>	
Controls	Good			<input type="checkbox"/>	
Seals	Good			<input type="checkbox"/>	
Torque Converter	Good			<input type="checkbox"/>	
Universal Joints	Good			<input type="checkbox"/>	
Lines / Fittings	Good			<input type="checkbox"/>	
Transmission - Reverse Shifts	Good			<input type="checkbox"/>	
Pump	Good			<input type="checkbox"/>	
Operating Condition	Good			<input type="checkbox"/>	
Transmission - Forward Shifts	Good			<input type="checkbox"/>	
Cooler	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Noisy	No			<input type="checkbox"/>	
Leaks	Yes			<input type="checkbox"/>	

.STEERING.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Front Axle	Good			<input type="checkbox"/>	

Steering Linkage	Good			<input type="checkbox"/>	
Tie Rods / Rod Ends	Good			<input type="checkbox"/>	
Steering Valves / Pumps	Good			<input type="checkbox"/>	
Steering Cylinder	Fair - left side leaking			<input type="checkbox"/>	
Oil Lines	Good			<input type="checkbox"/>	
King Pins	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	

.BRAKE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Type (Pedal, Lever)	Good - pedal			<input type="checkbox"/>	
Type (Wet, Dry)	Good - wet			<input type="checkbox"/>	
Control Valve	Good			<input type="checkbox"/>	
Lines	Good			<input type="checkbox"/>	
Parking Brake	Fair - park brake lamp inop			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

.TANDEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Tandems	Good			<input type="checkbox"/>	
Wheel Lugs & Rims	Good			<input type="checkbox"/>	
Differential	Good			<input type="checkbox"/>	
Differential Lock	Poor - diff lock on all the time			<input type="checkbox"/>	

.HYDRAULICS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Overall Operating Condition	Good			<input type="checkbox"/>	
Tank	Good			<input type="checkbox"/>	
Pumps & Valves	Fair - pump and control valves leaking			<input type="checkbox"/>	
Hose Lines	Good			<input type="checkbox"/>	
Linkage	Good			<input type="checkbox"/>	
Side Shift Cylinder	Good			<input type="checkbox"/>	
Lift Cylinders	Fair - balls need shimed			<input type="checkbox"/>	
Tip Cylinder	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	
Turn Drive Box	Good			<input type="checkbox"/>	
Circle, Shoes & Plates	Fair - needs shimed			<input type="checkbox"/>	
Circle A Frame	Good - needs shimed			<input type="checkbox"/>	
Circle Side Shift Cylinder	Good			<input type="checkbox"/>	
Ripper/Scar. Lift Cylinder	Good - lift gp.			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	Yes			<input type="checkbox"/>	

.BLADE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Face / Moldboard	Fair - needs shimed			<input type="checkbox"/>	
Cutting Edge Condition	Good			<input type="checkbox"/>	
Circle	Good			<input type="checkbox"/>	
A-Frame	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos

Blade Size	12ft with left hand ext.			<input type="checkbox"/>	
-------------------	--------------------------	--	--	--------------------------	--

.TIRES.

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	Photos
Right Front	Akuret	30	90	No	No	No	
Right Rear Center	Akuret	20	60	No	No	No	
Right Rear	Akuret	20	60	No	No		
Left Front	Akuret	30	90	No	No	No	
Left Rear Center	Akuret	20	60	No	No	No	
Left Rear	Akuret	20	60	No	No	Yes	
Tire Size	14.00-24						
Average Life Remaining	70						

Marketing Photos



















